A and S Property Inspector Property Inspection Report





, Las Vegas, NV Inspection prepared for: xxxxxx xxxxxx Real Estate Agent: . . -

> Date of Inspection: 10/22/2014 Age of Home: 1980 Size: 1598 Weather: Clear Dry

Inspector: Steven Montesano License # IOS.0001468-res 407 Park Way East, Las Vegas, NV 89106 Phone: 702-373-9519 Fax: 702-870-1293

Email: steve@aandsinspector.com www.aandsinspector.com

Report Summary

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expenses to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all of the pages of the report as the summary alone does not explain all the issues. All repairs must be done by a licensed &bonded trade or profession. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

Grounds

Page 8 Item: 7	Grounds Electrical	• Observed wires coming from garage vent. unknown. this needs to
0		be checked for use of wires by a licensed electrician
		 Outlet cover missing and are not waterproof
		 Junction box missing cover plate



Junction box missing cover plate

Observed wires coming from garage vent. unknown. this needs to be checked for use of wires by a licensed electrician

Page 10 Item: 16	Patio and Porch Condition	 Sagging/buckling on roof decking Exposed nails on roofing material. Recommend sealing all fastener heads Holes in roof Flashing appears inadequate The structure covering the patio was poorly attached to the home at the time of the inspection. The Inspector recommends corrections by a qualified contractor.
Exterior Areas		
Page 11 Item: 2	Window Condition	 Observed some window glass broke/damaged
Roof		
Page 14 Item: 1	Roof Condition	 Recommend roofing contractor to evaluate. Appears to have been prior repairs

	0			
Visible	deterioration was note	ed. Appears to have been prior repairs		
Page 14 Item: 2	Flashing	 Recommend review by a licensed roofer for repair or replacement as necessary. Poor roof flashing- it appears there are no drip edges installed. 		
Page 14 Item: 3	Soffit/fascia Condition	 Observed separation/deterioration of fascia Observed water stains at corner(s) of fascia boards 		
	Obs	erved curling tile at penetration		
Page 15 Item: 5	Penetration Condition	Observed tiles curling at some penetrations		

	Ob	served curling tile at penetration
Floatrical	05	
Electrical Page 17 Item: 1	Electrical Panel	• We recommend contacting a licensed electrician to evaluate and
		repair the issues. Open breaker panel slot(s) at panel box cover. Electrocution hazard. Noted open wires in box When panel cover off there is a lot of wires in box which obstructs a full inspection of the main panel
Garage	over off there is a lot of Walls Condition	of wires in box which obstructs a full inspection of the main panel
Page 19 Item: 1	vvalis Condition	 Observed prior stain on ceiling and wall Fire wall between garage & house needs repair for fire standards

		05/08/2010 15.34	
Observed p	prior stain on ceiling	and wall	Fire wall between garage & house needs repair for fire standards
Page 19 Item: 4	Electrical Conditi	on • Recommer • Observed e	nd full review by qualified electrical contractor electrical wires in access area, this is safety hazard
	Recommen	d full review by c	ualified electrical contractor
Page 20 Item: 8	Fire Door		observed the self-closing devices (of swinging doors) and latch the door completely when operated from position.
Interior Areas	1	I	
Page 23 Item: 3	Ceiling Fans	• The ceiling light electric	fan in living room appears to be jumped off of main

Page 24 Item: 9	Smoke Detectors	 SAFETY CONCERN: The smoke alarm(s) did not operate when tested. You need to be alerted in case of a fire. Recommend repair or replacement of the smoke alarm. Although smoke detectors were installed in the home at the time of the inspection, their placement did not meet modern safety requirements. Although homes are only required to comply with building codes regulating smoke detector placement which were in effect at the time the home was originally constructed or underwent major renovations, for safety reasons, the Inspector recommends compliance with modern safety standards. Consider installation of additional smoke detectors to bring the home into compliance with modern building requirements. Generally-accepted current standards require smoke detectors in the following locations: In the immediate vicinity of the bedrooms In all bedrooms In each story of a dwelling unit, including basements and cellars, but not including crawl spaces and uninhabitable attics. 			
Page 25 Item: 14	Fireplace	 The fireplace front/screen assembly is not affixed to the opening of the chimney and has a towel stuffed in between. have a fireplace professional evaluate and repair any issues as necessary. 			
Laundry					
Page 27 Item: 7	Exhaust Fan	• Exhaust fan did not operate at time of inspection.			
Kitchen		· · · · ·			
Page 31 Item: 10	Vent Condition	• Observed air leaking from duct when exhaust fan operated, this should be sealed to allow exhaust to vent to the exterior			

05/06/2009 15:29

Observed air leaking from duct when exhaust fan operated, this should be sealed to allow exhaust to vent to the exterior

Attic	
Page 37 Item: 2	• Evidence of past leaking noted. The area tested dry. Recommend monitoring for future leaking.

We appreciate the opportunity to conduct this inspection for you! Please carefully read your entire Inspection Report. Call us after you have reviewed your report, so we can go over any questions you may have. Remember, when the inspection is completed and the report is delivered, we are still available to you for any questions you may have, throughout the entire closing process. Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible portion of the structure; inspection may be limited by vegetation and possessions. Depending upon the age of the property, some items like GFI outlets may not be installed; **this report will focus on safety and function, not current code**. This report identifies specific noncode, non-cosmetic concerns that the inspector feels may need further investigation or repair. For your safety and liability purposes, we recommend that licensed contractors evaluate and repair any critical concerns and defects. Note that this report is a snapshot in time. We recommend that you or your representative carry out a final walk-through inspection immediately before closing to check the condition of the property, using this report as a guide.

Inspection Details

1. Attendance

In Attendance: Client present • Buyer Agent present

2. Home Type

Home Type: Single Family Home

3. Occupancy

Occupancy: Vacant

Grounds 1. Driveway and Walkway Condition Good Monite Poor N/A None Materials: Concrete driveway • Concrete walkway Х 2. Grading Good Monite Poor N/A None Х 3. Vegetation Observations None Good Monite Poor N/A Observations: Inspector suggests removal of the vegetation to close to structure Х 4. Gate Condition Good Monite Poor N/A None Materials: Metal Observations: Х • Gate column not secured. 5. Patio and Porch Deck Good Monite Poor N/A None Observations: • Cracks in patio floor Х 6. Stairs & Handrail Good Monite Poor N/A None Х 7. Grounds Electrical Good Monite Poor N/A None **Observations:** • Observed wires coming from garage vent. unknown. this needs to be checked for Х

- use of wires by a licensed electrician
- Outlet cover missing and are not waterproof
- Junction box missing cover plate




Junction box missing cover plate

Observed wires coming from garage vent. unknown. this needs to be checked for use of wires by a licensed electrician







9. Main Gas Valve Condition None



Materials: Main gas shut off located at outside meter • The gas service is off to the structure. The inspector cannot inspect this system

10. Plumbing

Good Monite Poor N/A None



Materials: Undetermined






12. Pressure Regulator Good Monite Poor

N/A None **Observations:**




Inspector could not locate pressure regulator

13. Exterior Faucet Condition



14. Balcony






Exterior Areas







2. Window Condition

Good	Monite r	Poor	N/A	No
	1		1	1

Х

Observations:

• Seal gaps or cracks in walls and around doors and windows where moisture may penetrate with an appropriate sealant or paint, and as a routine maintenance

- Window(s) did not operate correctly, repair or adjustment as needed
- Clean window tracks for better operation
- Some window screens missing/damaged
- Observed deterioration of some window pane seals
- Observed some window glass broke/damaged

3. Security Bars/Doors



4. Siding Condition

Good	Monite r	Poor	N/A	None	_
	Х				

Materials: Stucco

Observations:

MAINTANCE TIP: Caulk and seal all gaps, cracks and openings
Observed normal/ moderate cracks

5. Patio Doors Good Monite Poor

Х

N/A None Observations:

• The door tracks appeared dirty making the door difficult to operate. Inspector recommend cleaning the tracks and lubricating the doors rollers


6. Screen Doors






7. Satellite/Cable condition

Good Monite Poor N/A None Observations:



Observed cover missing from phone box

8. Exterior Conditions





Foundation

1. Slab Foundation

Good Monite Poor N/A None



2. Foundation Perimeter






3. Foundation Walls

Good Monite Poor N/A None



4. Cripple Walls

Good Monite Poor N/A None



5. Foundation Plumbing

Good Monite Poor N/A None Observations:


6. Sump Pump

Good Monite Poor N/A None




7. Crawl Space Condition

Good Monite Poor N/A None




8. Ventilation

Good Monite Poor N/A None



9. Vent Screens


Good Monite Poor N/A None



10. Access Panel



11. Post and Girders



Roof

1. Roof Condition



Х

Materials: There are areas of the roof that were not visible to inspector at time of inspection and were not inspected • Inspected from ground level with binoculars. Materials: Asphalt shingles noted. • Rolled roofing noted. Observations:

• MAINTEANENCE TIP: Weather permitting, keep debris cleared from roof valleys to extend life of roof.

- Appears to may have multiple layers
- Caulk and seal all gaps/cracks and openings..
- Visible deterioration was noted.
- Exposed nails on roofing material. Recommend sealing all fastener heads.
- Observed some shingles damaged.
- Recommend roofing contractor to evaluate.
- Appears to have been prior repairs




Visible deterioration was noted.

Appears to have been prior repairs

2. Flashing

Good Monite Poor N/A None




Observations:

• Typical maintenance necessary, now and on an annual or semi-annual basis. This generally consists of resealing gaps at through-the-roof projections

- Recommend review by a licensed roofer for repair or replacement as necessary.
- Poor roof flashing- it appears there are no drip edges installed.

3. Soffit/fascia Condition





- Paint peeling. Repair as needed
- Observed separation/deterioration of fascia
- Observed water stains at corner(s) of fascia boards




Observed curling tile at penetration

Observed separation/deterioration of fascia

4. Eaves & Facia





Observations: • Peeling paint observed, suggest scraping and painting as necessary.

5. Penetration Condition



Observations: Observed tiles curling at some penetrations




Observed curling tile at penetration

6. Ventilation




7. Vent Screens






8. Gutters





9. Spark Arrestor





10. Chimney

Good	Monite r	Poor	N/A	None	. (
	X				•

Observations: • Some mortar deterioration observed; advise repair as needed.



Some mortar deterioration observed; advise repair as needed.

Electrical

1. Electrical Panel



Х

Location: Exterior of structure


Location: No Sub Panels located

- Observations:
 - Breakers NOT clearly marked.
 - We recommend contacting a licensed electrician to evaluate and repair the issues.
 - Open breaker panel slot(s) at panel box cover. Electrocution hazard.
 - Noted open wires in box
 - When panel cover off there is a lot of wires in box which obstructs a full
- inspection of the main panel



When panel cover off there is a lot of wires in box which obstructs a full inspection of the main panel


2. Main Amp Breaker




```
Observations:

• unknown
```

3. Breakers in off position






4. Cable Feeds






5. Breakers






6. Condition

Good Monite Poor N/A None Materials: Copper



7. Service Entrance Conditions

Good Monite Poor N/A None




8. Fuses

Good Monite Poor N/A None r



Materials: No fuses in this property.


9. General Condition



Garage

1. Walls Condition

Good Monite Poor N/A None



_ Observations:

- Typical cosmetic damage observed on walls throughout the garage
- Personal items block complete inspection of some floors, walls and ceiling areas
 Observed patching on walls
- Observed patching on walls
- Observed prior stain on ceiling and wall
- Fire wall between garage & house needs repair for fire standards






Observed prior stain on ceiling and wall


Fire wall between garage & house needs repair for fire standards


2. Floor Condition





3. Rafters & Ceiling





4. Electrical Condition

Х

N/A

Good Monite Poor

None Observations:

• Outlet cover plates missing

- Recommend full review by qualified electrical contractor
- Observed electrical wires in access area, this is safety hazard


A and S Property Inspector



Recommend full review by qualified electrical contractor


5. GFCI






6. 240 Volt

Good Monite Poor N/A None



7. Exterior Door

Good Monite Poor N/A None



8. Fire Door

Good Monite Poor N/A None

Observations:

• Inspector observed the self-closing devices (of swinging doors) do not close and latch the door completely when operated from the full open position.


9. Garage Door Condition

Good Monite Poor N/A None Materials: Sectional door




10. Garage Door Parts


Good Monite Poor N/A None




11. Garage Opener Status



12. Garage Door's Reverse Status





13. Ventilation

Good Monite Poor N/A None Observations:



• Observed vents covered by dry-wall/ cabinets

14. Vent Screens

Good Monite Poor N/A None



Observations:
Vent screens are damaged or missing, suggest repairing or replacing screens as necessary

15. Cabinets





• Cabinet door(s), shelving missing/damaged

16. Counters




17. Wash Basin

Good Monite Poor N/A None



18. Car Port Condition





Interior Areas


The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.




2. Cabinets





3. Ceiling Fans



4. Closets



Observations:
Stains were present on the closet ceilings indicating prior water infiltration.
Although they tested dry they should be noted.

5. Door Bell



None




6. Doors



7. Electrical

Good Monite Poor N/A None



Observations:Outlet cover plates missing.

• Was not able to identify switch operation on a number of switches

8. Security Bars





9. Smoke Detectors



_ Observations:

• MAINTENANCE: Periodic testing and changing batteries yearly to ensure proper Smoke Alarm operation is required.

• IMPROVE: There was no visible CO (Carbon Monoxide) detector(s) in the home. The Consumer Product Safety Commission recommends that every residence with fuel-burning (gas) appliances be equipped with a UL Listed CO alarm. CO is colorless and odorless and thus impossible to detect without a proper electronic detector. At a minimum, put an alarm near the sleeping rooms on each level in your home. For the most trouble-free operation, I recommend the plug-in type -- not the battery operated type -- with digital readout that tells you the peak CO concentration whenever you push the peak level button.

SAFETY CONCERN: The smoke alarm(s) did not operate when tested. You need to be alerted in case of a fire. Recommend repair or replacement of the smoke alarm.
Although smoke detectors were installed in the home at the time of the inspection, their placement did not meet modern safety requirements.

Although homes are only required to comply with building codes regulating smoke detector placement which were in effect at the time the home was originally constructed or underwent major renovations, for safety reasons, the Inspector recommends compliance with modern safety standards.

Consider installation of additional smoke detectors to bring the home into compliance with modern building requirements.

Generally-accepted current standards require smoke detectors in the following locations:

In the immediate vicinity of the bedrooms

In all bedrooms

•In each story of a dwelling unit, including basements and cellars, but not including crawl spaces and uninhabitable attics.

10. Stairs & Handrail



11. Window/Wall AC/Heat





12. Ceiling Condition

Good Monite Poor N/A None



Х

Materials: There are drywall ceilings




• Typical cosmetic damage noted on ceiling throughout the home.


13. Wall Condition



Materials: Drywall



• Typical cosmetic damage noted on walls throughout the home.



Laundry

1. Locations

Locations: Interior room


2. Cabinets





3. Counters





4. Dryer Vent

Х



Observations:

 MAINTANCE: The Inspector recommends that you have the dryer vent cleaned at the time of purchase and annually in the future to help ensure that safe conditions exist. Lint accumulation can occur even in approved, properly installed vents.
 The dryer vent is missing the exterior cover.



The dryer vent is missing the exterior cover.


5. Electrical





6. GFCI

Good Monite Poor N/A None




7. Exhaust Fan

Good Monite Poor N/A None

Observations: • Exhaust fan did not operate at time of inspection.

8. Gas Valves






9. Wash Basin





10. Floor Condition





Materials: Tile



11. Plumbing





12. Wall Condition

Good Monite Poor N/A None

X

Materials: Drywall walls noted.

13. Ceiling Condition



Materials: There are drywall ceilings noted.


14. Washer/Dryer condition

Good Monite Poor N/A None



Observations: • Not tested/inspected

15. Door Condition




Heat/AC

The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.


The inspector will usually test the heating and air conditioner using the thermostat or other controls. If the air temperature out side is above 65 the testing of the heat may damage the unit therefore it will not be tested. If the temperature out side is below 65 the testing of the A/C may damage the unit therefore it will not be tested. For a more thorough investigation of the system please contact a licensed HVAC service person.


1. Heater Condition



• Not inspected gas off to unit.

2. Heater Base





3. Enclosure






4. Venting




5. Gas Valves

Good Monite Poor N/A None




6. Refrigerant Lines






7. AC Compress Condition






Compressor Type: Electric Location: The compressor is located on the roof. (Package unit)

8. Air Supply



9. Registers





10. Filters



Location: Located inside a filter grill in the hall ceiling.

Observations:


• MAINTENANCE TIP: The air filter(s) should be inspected at least monthly and cleaned or replaced as required. There are two types of filters commonly used: (1) Washable filters, (constructed of aluminum mesh, foam, or reinforced fibers) these may be cleaned by soaking in mild detergent and rising with water. Or (2) Fiberglass disposable filters that must be REPLACED before they become clogged. Remember that dirty filters are the most common cause of inadequate heating or cooling performance.

11. Thermostats



12. Swamp Cooler Condition

Good	Monite r	Poor	N/A	None



Kitchen

The kitchen is used for food preparation and often for entertainment. Kitchens typically include a stove, dishwasher, sink and other appliances.

1. Cabinets




2. Counters



Dishwasher



4. Garbage Disposal







5. Microwave

Good Monite Poor N/A None




6. Cook top Condition





7. Oven Condition

Good Monite Poor N/A None



8. Range Condition



Х

Observations:



• Gas off not inspected.

Sinks





10. Vent Condition





Materials: Exterior Vented • Part of Microwave

Observations:

• Maintenance Tip: Filter under microwave should be inspected and cleaned periodically

• Vent filter/screen missing/dirty. Recommend cleaning filter regularly for fire safety.

• Observed air leaking from duct when exhaust fan operated, this should be sealed to allow exhaust to vent to the exterior



Observed air leaking from duct when exhaust fan operated, this should be sealed to allow exhaust to vent to the exterior


11. Floor Condition



None




12. Wall Condition




Materials: Drywall walls noted.

13. Plumbing

Х





14. Ceiling Condition



Materials: There are drywall ceilings noted.


Observations:

• The drywall is patched in areas. The reason for the patch could not be determined.

• Observed small seam crack in the ceiling finish

15. Electrical

-					
Good	Monite	Poor	N/A	None	



A and S Property Inspector

16. GFCI

Good Monite Poor N/A None




17. Refrigerator Condition





18. Trash Compactor



Bedrooms

The main area of inspection in the bedrooms is the structural system. This means that all walls, ceilings and floors will be inspected. Doors and windows will also be investigated for damage and normal operation. Personal items in the bedroom may prevent all areas to be inspected as the inspector will not move personal items.

1. Locations

Locations: Master bedroom#1 • Bedroom 2 • Bedroom 3 • Den

2. Cabinets




3. Ceiling Fans

Good Monite Poor N/A None



4. Closets






Noted stain on closet ceiling

5. Electrical






6. Floor Condition



Page 33 of 38

7. Wall Condition






_ Materials: Drywall walls noted.

Observations:

• Typical cosmetic damage noted on walls throughout the home.


8. Window-Wall AC or Heat





9. Ceiling Condition

Good Monite Poor N/A None



Materials: There are drywall ceilings

10. Doors

Х		

Bathroom

Bathrooms can consist of many features from jacuzzi tubs and showers to toilets and bidets. Because of all the plumbing involved it is an important area of the house to look over. Moisture in the air and leaks can cause mildew, wallpaper and paint to peel, and other problems. The home inspector will identify as many issues as possible but some problems may be undetectable due to problems within the walls or under the flooring..

1. Locations

Locations: Master Bathroom • Hall bathroom

2. Cabinets







Materials: There are drywall ceilings



4. Counters



5. Electrical




6. GFCI

Good Monite Poor N/A None



7. Exhaust Fan

Good Monite Poor N/A None




Observations: • Exhaust fan is inoperable. Hall bathroom


8. Floor Condition

Good Monite Poor N/A None



9. Heating






10. Plumbing








12. Shower Walls



13. Bath Tubs






14. Enclosure





15. Sinks





16. Toilets





Recommend review for repair or replacement as necessary.
Toilet clogged did not flush at time of inspection Master bath

17. Doors

Good	Monite	Poor	N/A	None
	r			




Attic 1. Access Good Monite Poor N/A None Х 2. Structure Good Monite Poor N/A None **Observations:** • Inspected from access only, limited space in attic prevented entry. Х Evidence of past leaking noted. The area tested dry. Recommend monitoring for future leaking. 3. Duct Work Good Monite Poor N/A None Х 4. Electrical Good Monite Poor N/A None **Observations:** All wiring should be properly secured to the framing. Х 5. Attic Plumbing Good Monite Poor N/A None Х 6. Insulation Condition Good Monite Poor N/A None Materials: Rock Wool Depth: Insulation averages about 6-8 inches in depth Х **Observations:** • Insulation moved in areas. • This type of insulation obstructs a visual inspection of many areas in attic

This type of insulation obstructs a visual inspection of many areas in attic

12/102/20000 92079

7. Exhaust Vent





8. General Condition



Observations: • There are some area's that are not visible and are not inspected